City of Detroit WATER AND SEWERAGE DEPARTMENT INTRA-DEPARTMENTAL MEMO

FROM: DWS-844A Evaluation Team
(b)(6), (b) (7)(C)

THRU: (b)(6), (b) (7)(C)

TO: (b)(6), (b) (7)(C)

Deputy Director
(b)(6), (b) (7)(C)

COPY: (b)(6), (b) (7)(C)

RE: Evaluation Committee Negotiations Recommendations

DWSD Contract No. DWS-844A (Security Systems Upgrade for Various

Booster Pumping Stations)

This memorandum presents the recommendation of the Evaluation Committee for the above-referenced contract to commence negotiations with only the highest ranked proposer, namely, Motor City Electric Company (MCE). The Evaluation Committee also recommends forgoing negotiations with the second-ranking proposer, namely, the DFT Security Team (DFT), forgoing negotiations with the second-ranking proposer, namely, the DFT Security Team (DFT), forgoing this contract could not be unless DWSD determines that an agreement with MCE regarding this contract could not be reached.

Subsequent to three cost proposal clarification rounds with each of the two highest-ranked proposers (i.e., DFT and MCE), and as demonstrated by the attached "cost comparison summary" tabulation, the Evaluation Committee's recommendation is based on the determination that:

- (a) MCE's design costs are substantially lower than DFT's, partly due to the fact that MCE's proposal included a more defined and developed design than that presented by DFT;
- (b) MCE's training costs are lower and more commensurate with the level of effort required in the Request For Proposals (RFP); and
- (c) MCE's construction costs, mobilization and demobilization costs, as well as the "general conditions" costs are significantly lower than DFT's.


The Evaluation Committee also recommends negotiation of additions and deletions that are estimated to potentially result in a credit amount of approximately \$ 2.4m from MCE versus an estimated credit amount of approximately \$ 1.27m from DFT, based on the scope and prices of the respective proposers

Given that the respective proposed costs by DFT and MCE for this contract are approximately \$ 20.73m and \$ 16.31m, the gap between DFT's and MCE's proposed costs for this contract may further widen in the event DWSD is successful in negotiating the full amount of its estimated credits. A separate tabulation for each of the two proposers is attached to this memorandum, outlining the anticipated additions and deletions, and providing respective cost estimates.

DWS-844A Recommendation Page 2

It is noted that although the Evaluation Committee did identify some deficiencies in MCE's proposal, the Evaluation Committee remains confident that MCE's proposal is a better value to DWSD than DFT's, and that the identified deficiencies can be rectified during negotiations and possibly without increasing MCE's proposed price.

If you concur with the Evaluation Committee's recommendation, please indicate below.



Proposed Additions/ Credits to the MCE Bid

Net Change to Contract

		(\$2,395,466)
1. Net Change		[42]303,700)
Additions to Contract	Type of Change (See Notes)	Cost
Wordings to animate		•
Farmington- 1 camera apparently missed for top of Reservoir	Deficiency	~ O
Farmington - I carrier a apparently missed Ford Road- 3 or 4 cameras apparently missed	Deficiency	. 0
3. Imlay- 3 cameras apparently missed	Deficiency	0
Imitay- 3 cameras apparently missed Joy Road- 2 cameras apparently missed	Deficiency	- ŏ
	Deficiency	Ö
North Service Center- 4 cameras apparently materials of reservoir Northwest- Missed camera coverage of hatch at south-east of reservoir	Deficiency	ŏ
z echoolcraft. 2 cameras apparently missed	Deficiency Deficiency	Ō
8. West Chicago- 2 cameras apparently missed	Deficiency	. 0
a tarak Bood, 2 or 3 cameras apparently misseu	Addition	75,000
A A A WAR A STRONG TO Administration Packing Lot at Cor	Addition	10,000
	Addition	2,000
TARTERIAL USE MOSCOTIV TO DICIN IN INCHES AND THE TERMINAL	Addition	3,000
	Change	2,000
the order on one of the double ducis on the open	Change	2,000
	Change	30,000
As North Service Center-locate carriera poles un east side at the	Change	10,000
47 Schoolcraft- coordination with DVVS-603 Work	Change	20,000
) — — — — — — — — — — — — — — — — — — —	Change	30,000
The security of the security o	Addition	2,000
	Change	3,000
The second of th	Change	3,000
	Change	10,000
	Change	10,000
23. West Service Center- custom permeter socially 24. West Service Center- bring out secured fence to encompass valve pit	Total	\$212,000
Notes: Deficiency - Deficiency in the MCE design. Deficient cameras will be		
Deficiency- Deficiency in the Wice design: Doublet		• , , , , , , , , , , , , , , , , , , ,
negotiated for \$0 cost.		
Addition- Additions needed by DWSD Change Per further design and evaluation of this project, Consultants Per further design and evaluation of this project, Consultants		
Change Per further design and evaluation of this project and DWSD Engineering have identified potential change orders.		
and DAADD Eligineering lights in the		Cast
Credits to Contract	Page 1	Cust
	· r	(2,323,227)
Utilinet Radio Backup System See Note 1 Utilinet Radio Backup System See Note 1	•	(87,239)
Utilinet Radio Backup System See replaced by the OPT-E-MAN system Delete shared T-1 option since replaced by the OPT-E-MAN system	••	(10,000)
a Bouga evicting fahric for temporary lendes		(25,000)
		(150,000)
		(12,000)
5. Delete security at Beile Isle Sewage that to Michigan Ave- delete cameras for No.1 Reservoir planned for demolition		(\$2,607,466)
	Total	famina, i, - at
Note 1. The Utilinet system is recommended to be deleted due to its higher		
than expected cost and technical problems		
Cities acclements in an	S	- *

(\$1,273,500)

Proposed Additions/ Credits to the DFT Bid

Net Change to Contract

		(41,613,000)
, Net Change		•
	Type of	
	Change (See	-
Additions to Contract	Notes)	Cost
Additions to contract	•	•
1. Farmington- 1 camera apparently missed for top of Reservoir	Deficiency	0
1. Farmington- 1 camera apparency missed	Deficiency	0
Adams Road- 1 camera apparently missed Eastside closer camera coverage of the southwest corner is reqr'd Eastside closer camera coverage of the southwest corner is reqr'd	Deficiency	. 0
3. Eastside doser camera coverage of the social state.	Deficiency	0
4. Haggerty Road -2 cameras apparently missed	Deficiency	0
5. Imlay- 1 camera apparently missed	Deficiency	0
6. Michigan Reservoir- 2 cameras apparently missed	Deficiency	0
7. Schoolcraft- 2 cameras apparently missed	Deficiency	. 0
o Most Chicago- 2 cameras apparently missed	Deficiency	0
a version blood 2 or 3 cameras apparently misseu	Addition	75,000
The state of the property of the property of the state of	Addition	10,000
	Addition	2,000
	Addition	3,000
The same of the in new DWS-87 (life digiti system to see any	Change	2,000
	Change	30,000
La Minute Contine Content locate carriera poles un east side of	Change	10,000
Coordination with LIVVA-833 WUIN	Addition	2,000
	Change	3,000
	Change	3,000
	Change	10,000
	Change	10,000
20. West Service Center- dustom perimeter account of the compass valve pit 21. West Service Center- bring out secured fence to encompass valve pit		\$160,000
21, 44696 93.415	Total	4
	-	•
Nation		
Notes: Deficiency Deficiency in the DFT design, however their bid did include a		•
Deficiency Deficiency in the DT coagurage. The remainder deficient		
cameras will be negotiated for \$0 cost.		4
a turisma and of by DWSD		
and evaluation of this project, Consumer		
Change Per further design and evaluation of this project change orders and DWSD Engineering have identified potential change orders.		
SUG DANSED ELIGINEERING HISTORISATION LA	4	Canb
Credits to Contract		Cost
Cladica to countral		(4.447 500)
Contam Con Note 1		(1,117,500)
1. Utilinet Radio Backup System See Note 1	, t ₁	(119,000)
Utilinet Radio Backup System Good Note Delete shared T-1 option since replaced by the OPT-E-MAN system		(10,000)
a mayor existing fabric for temporary relices.	. •	(25,000)
		(150,000)
		(12,000)
5. Delete security at Belle Isle Sewage due to 1. 6. Michigan Ave- delete cameras for No 1 Reservoir planned for demolition	Total	(\$1,433,500)
	1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	
Note 1. The Utilinet system is recommended to be deleted due to its higher	· -	*
than expected cost and technical problems.		
en e		